

The State of Utah

Department of Natural Resources

Division of Oil, Gas & Mining

ROBERT L. MORGAN Executive Director

LOWELL P. BRAXTON Division Director OLENE S. WALKER
Governor

GAYLE F. McKEACHNIE
Lieutenant Governor

Representativ	es Present During the Inspection:	
Company	Dennis Ware	
OGM	Steve Demczak	

Inspection Report

Permit Number:	C0070038
Inspection Type:	PARTIAL
Inspection Date:	Wednesday, April 27, 2011
Start Date/Time:	4/27/2011 1:00:00 PM
End Date/Time:	4/27/2011 2:00:00 PM
Last Inspection:	Wednesday, March 23, 2011

Inspector: Steve Demczak,
Weather: Windy, Low 50's, Cloudy
InspectionID Report Number: 2725

Accepted by: jhelfric 5/3/2011

Permitee: PLATEAU MINING CORP
Operator: PLATEAU MINING CORP
Site: WILLOW CREEK MINE

Address: PO BOX 30, HELPER UT 84526-0030

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current Acreages

Mineral	Ownership	Types of C

Types of Operations

62.49	Total Permitted	✓	Federal	~	Underground
71.44	Total Disturbed		State		Surface
25.41	Phase I		County	✓	Loadout
92.45	Phase II	✓	Fee		Processing
92.45	Phase III	✓	Other		Reprocessing
	71.44 25.41 92.45	92.45 Phase II	71.44 Total Disturbed 25.41 Phase I 92.45 Phase II ✓	71.44 Total Disturbed ☐ State 25.41 Phase I ☐ County 92.45 Phase II ✓ Fee	71.44 Total Disturbed State 25.41 Phase I County 92.45 Phase II Fee

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Inspector's Signature:

Steve Demozak,

Date

Thursday, April 28, 2011

Inspector ID Number: 39





Permit Number: C0070038 Inspection Type: PARTIAL

Inspection Date: Wednesday, April 27, 2011

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	✓		✓	
2.	Signs and Markers	V		~	
3.	Topsoil	✓		✓	
4.a	Hydrologic Balance: Diversions	✓		~	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments				
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments				
8.	Noncoal Waste	✓		~	
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage	~		✓	
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading	✓		✓	
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.8	a Roads: Construction, Maintenance, Surfacing	✓		V	
16.t	Roads: Drainage Controls	✓		✓	
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations	V		~	
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Permit Number: C0070038 Inspection Type: PARTIAL

Inspection Date: Wednesday, April 27, 2011

Page 3 of 3

1. Permits, Change, Transfer, Renewal, Sale

The permittee did receive anther five year permit from DOGM. Next month will be a complete with more information.

2. Signs and Markers

The identification signs is next to the road to the property. The information meets the R645 Coal Rules.

3. Topsoil

All topsoil was used in reclamation.

4.a Hydrologic Balance: Diversions

The diversions were opened and functioning as designed.

8. Noncoal Waste

The site is clear of non-coal waste material.

10. Slides and Other Damage

The shafts at Crandall were inspected with minor subsidence. A guess is 1-2 feet of settling.

12. Backfilling And Grading

The total disturbed area is reclaimed and is backfilled and graded.

16.a Roads: Construction, Maintenance, Surfacing

Some rocks did fall on to the road during the winter.

16.b Roads: Drainage Controls

Diversions and culverts were open.

18. Support Facilities, Utility Installations

There are no facilities.